

106

OFFICE OF THE CHIEF ENGINEER, P.W.D., RAJASTHAN,
JAIPUR.

CIRCULAR No. 2/2005

No. SE (PMGSY) CIRCULAR 2005/D-2378 Date: 14/06/05

It has been observed that the constructions of shoulders (hard / earthen) on either side of the pavement are not found in accordance with the specifications and in conformity with lines, grades, cross slope & compaction. It is also noticed that sequence of operation is not maintained in construction of shoulders in layers, matching the thickness of adjoining pavement layers.

It is therefore, enjoined upon all field officers of the department to ensure checking of line, grade, cross fall & compaction of shoulders according to the specification for Rural Road. The Superintending Engineer should ensure the compliance of these instructions before payment to the contractor.

Please acknowledge the receipt of this circular.

[Handwritten Signature]
14/6/2005

Chief Engineer cum Addl. Secretary,
P.W.D., Rajasthan, Jaipur.

Copy to the following for information & necessary action please:-

1. The PS to Hon'ble PWD Minister, Govt. of Rajasthan, Jaipur.
2. The Principal Secretary to Govt. PWD, Rajasthan, Jaipur.
3. The Addl. Chief Engineer, PWD Zone _____ (All.)
4. The Superintending Engineer, P.W.D. Circle _____ (All)
5. The Executive Engineer, PWD, Division _____ (All).
6. The Sr. PA to CE/CE(R) (NH) All SE's & EE's in CE's Office.
7. PFCGE

[Handwritten Signature]

Chief Engineer cum Addl. Secretary,
P.W.D., Rajasthan, Jaipur.

14/6/2005