

CIRCULAR NO. 03/2007-08

During inspection of existing roads and new roads in hilly area, it has been observed that no proper care is being taken for drainage of rain water, geometric designs of curves both horizontal and vertical and road safety works for roads being constructed/maintained in hilly area. Without proper drainage, water flows all along the B/T edge or over the road surface with high velocity causing severe damages to road structure. Even the existing drainage system of these hilly roads is not properly maintained, the drains are not cleaned before rainy season.

The field officers are instructed to incorporate all such provisions for the projects to be taken in hilly areas. The instructions may also be issued to Asstt. Engineer/Jr. Engineers for keeping proper maintenance of such existing drainage system. The Superintending Engineers are hereby made responsible for compliance of such instructions.


CHIEF ENGINEER (R-I)

Copy to following for information/necessary action:

1. P.S. to Principal Secretary to Govt., PWD Raj., Jaipur.
2. P.S. to Secretary to Govt., PWD Raj., Jaipur.
3. Chief Engineer & Addl. Secy., PWD Raj., Jaipur.
4. Chief Engineer (R-II)/(NH)/(PMGSY) PWD Raj., Jaipur.
5. Addl. Chief Engineer (all)
6. Superintending Engineer (all)
7. Executive Engineer (all)


CHIEF ENGINEER (R-I)