

OFFICE OF THE CHIEF ENGINEER, PWD RAJASTHAN
JAIPUR

No.

Dated: 23/7/12

CIRCULAR

In Medical colleges & their attached hospitals of the state, the Operation Theatre, ICU and all Wards are shelter for patients & thus regular repair & maintenance of these buildings play a very vital role.

Copy to all SE

It has been observed that concerned Engineers do not examine these buildings regularly specially for the RCC roofs / ceiling to avoid the possibility of falling of loose ceiling plaster.

recd by me

Recently, One such accident has taken place on 16.09.2011 at MDM Hospital Jodhpur wherein RCC ceiling plaster along with concrete cover of ceiling of Blood Bank in Operation Theater no. 5 has fallen down damaging the false ceiling.

It is therefore enjoined upon all concerned Engineers that these buildings should be examined at least once in 6 months for safety & a safety certificate be obtained, so as to monitor this task to avoid such accidents in future.

store

Chief Engineer cum Addl. Secy.,
PWD Rajasthan, Jaipur.

30/1/12

No. CE/SE (B)/PWD/JD - 1119

Dated: 30/1/2012

Copy to following for information & necessary action:-

1. P.S. to Principal Secretary to Hon'ble CM Govt. of Rajasthan.
2. P.S. to Hon'ble Minister, PWD Govt. of Raj., Jaipur.
3. S.A. to Hon'ble Minister of State, PWD Govt. of Raj., Jaipur.
4. Chief Engineers & Addl. Secy./CE(Roads)/CE(PMGSY)/ CE(SS), PWD Rajasthan.
5. MD, RSRDCC Jaipur.
6. Addl. Chief Engineers, PWD Rajasthan, Zone-Ajmer.... (All)
7. Superintending Engineer, PWD Rajasthan, Circle-..... (All)
8. Executive Engineer, PWD Dn.-(All). They are directed to percolate these directions to all AENs/JENs working under them for compliance.

No 10256-259

Date 03/02/2012

Copy to SE, PWD, circle Ajmer/Bhilwara/ Nagour/Tonk for inf & instructing your SE's & AE's for strict immediate compliance

Chief Engineer cum Addl. Secy.,
PWD Rajasthan, Jaipur.

30/1/12

B109